Idaho PUC Pipeline Safety Inspection Summary

Inspector(s):	Lec	ckie		Date(s):	6-10 May 2019
Company/Owner:		Avista		Unit/OPID:	D&A
Inspection Type & Time (1	day, 0.5 day)		Total In	spection Days:	5
Standard: Construction:	Training:	(T)(D) Integrity Ma	anagement:	Incident:	
M/M: Follow-up:	OQ:	Damage Preve	ention:	D&A:	5
Inspection Summary					
2019 Drug and Alcohol Program Inspection Avista Utilities					
May 6, 2019: (1 D&A)					
Traveled to Spokane, WA					
May 7-8, 2019: (2 D&A) Joe Leckie of the Idaho Public Utilities Commission met with Avista's Randy Bareither (Pipeline Safety Engineer) and Hallie Rowland (DER) at Avista's headquarters in Spokane, WA to review their DOT Anti-Drug and Alcohol Plan. PHMSA's Substance Abuse Program Comprehensive Audit and Inspection Protocol Form # 3.1.11 Rev 2 was used as a guide throughout the audit to ensure all areas were completed. This audit was conducted jointly with Washington's UTC who led the inspection.					
As a result of the inspection, the MIS Data Collection Forms have revealed that Avista's consortium contractor pool may not have met the required 50 percent testing rate.					
May 9, 2019: (1 D&A) Traveled to Boise, ID					
May 10, 2019: (1 D&A)					
Typed the inspection report, completed forms: PHMSA Substance Abuse Program Comprehensive Audit and					
Inspection Protocol Form # 3.1.11 Rev 2, IPUC Form 1 and attached inspection documents.					
Attached:					
PHMSA OPS Substance Abuse Program Comprehensive Audit and Inspection Protocol Form # 3.1.11 Rev 2					
IPUC Form 1, Inspection Summary					
Corrective Action Required: Yes X No					
Follow-up Required:	by (date):	Oct 31, 2019	Yes		
Close-out Letter Issued:	by (date).	00001, 2015	Yes		X
Inspector (Lead):				Date:	^
Reviewer:				Date:	